



Silicon Motion, Inc.

SM3257ENBA Test Program and ISP Release Note

**SM3257ENBA Test Program and ISP Release Note:**

Release Date	ISP Version	ISP Check Sum	Test AP Version	Description
2013/09/02	130902-BA	SM3257ENBAISP SM3257ENBAISP-ISPSA19nmTLC SM3257ENBAISP-ISPSA19nmTLC4P	V 2.5.27 v1 13/09/02 Build	<ol style="list-style-type: none"> 1. SM3257ENBA MP tool / FW first formal release 2. Support Samsung 1xnm ADG-M: K9ADGD8U0M 3. Support Samsung 1xnm ACG-B: K9ACGD8U0B 4. Support SanDisk 19nm 64Gb / 128Gb TLC: SDTNQCAMA-008G / SDTNQCAMA-016G 5. Support Micron 20nm 64Gb MLC L84A: MT29F64G08CBABA, MT29F64G08CBABB
2013/10/07	130905-BA 131002-BA 131002-BA 131002-BA 131002-BA 131002-BA 131002-BA	SM3257ENBAISP SM3257ENBAISP-ISPSA19nmTLC SM3257ENBAISP-ISPSA19nmTLC4P SM3257ENBAISP-ISPSD19nm SM3257ENBAISP-ISPSD19nm4P SM3257ENBAISP-ISPT19nm SM3257ENBAISP-ISPT19nm4P	V 2.5.27 v8 13/10/04 Build	<ol style="list-style-type: none"> 1. Update MPTool to fix Autohandler + Factory Driver can't scan UFD issue 2. Update SanDisk / Toshiba 19nm TLC FW to improve error handling in M0902. 3. Support Samsung 1xnm ABG-D: K9ABGD8U0D 4. Support Micron 20nm 128Gb MLC L85A: MT29F128G08CBCA